

Photo #	Photo Description	Date	Notes
001	10:30 A.M. - Scituate Reservoir Spillway, downstream side showing no spillage.	Mar. 13, 1936	
002	10:30 A.M. - Scituate Reservoir Spillway, upstream side showing elevation of Reservoir (283.69) 0.31 feet below crest.	Mar. 13, 1936	
003	10:30 A.M. - Scituate Reservoir Spillway, upstream side showing elevation of Reservoir (283.69) 0.31 feet below crest.	Mar. 13, 1936	
004	11:00 A.M. - Scituate Dam, Meter Chamber, looking north showing 200 MGD rate discharge to North Branch of the Pawtuxet River.	Mar. 13, 1936	
005	11:10 A.M. - Washington Avenue, City of Warwick, showing flood conditions at house on East Side.	Mar. 13, 1936	
006	11:10 A.M. - Washington Avenue, City of Warwick, showing flood conditions at house on West Side.	Mar. 13, 1936	
007	11:10 A.M. - Pawtuxet River at Elmwood Avenue Bridge looking west (upstream) showing water stage.	Mar. 13, 1936	
008	11:20 A.M. - Rear of Buildings, East Side of Elmwood Avenue looking south towards Pawtuxet River.	Mar. 13, 1936	
009	11:40 A.M. - Club Bagdad, Warwick Avenue, City of Warwick, looking Northeast towards Pawtuxet River.	Mar. 13, 1936	
010	11:50 A.M. - Pawtuxet River Reservation, State Nursery, East side of Warwick Avenue, looking east.	Mar. 13, 1936	
011	11:50 A.M. - Pawtuxet River at Warwick Avenue Bridge, looking west (upstream) showing water state at Bridge.	Mar. 13, 1936	
012	3:40 P.M. - Hope Dam, North Branch Pawtuxet River.	Mar. 19, 1936	
013	4:00 P.M. - Perennial Dye and Print Works, North Branch Pawtuxet River Clyde.	Mar. 19, 1936	
014	4:05 P.M. - Natick Dam, Pawtuxet River at Natick.	Mar. 19, 1936	
015	4:10 P.M. - Natick Flats, Pawtuxet River at Natick,	Mar. 19, 1936	
016	4:15 P.M. - Natick Flats, Pawtuxet River at Natick.	Mar. 19, 1936	

Photo #	Photo Description	Date	Notes
017	4:20 P.M. - Bald Hill Road, North of Pontiac Avenue, Warwick, R.I.	Mar. 19, 1936	
018	4:50 P.M. - First Avenue, Warwick, R.I.	Mar. 19, 1936	
019	5:00 P.M. - Looking East from Elmwood Ave. between First and Second Avenues, Warwick, R.I.	Mar. 19, 1936	
020	5:05 P.M. - Pawtuxet River at Elmwood Avenue looking west (upstream) showing water stage.	Mar. 19, 1936	
021	5:10 P.M. - Looking east from Elmwood Avenue north side of Pawtuxet River.	Mar. 19, 1936	
022	5:15 P.M. - Rear of buildings, east side of Elmwood Avenue looking south towards Pawtuxet River.	Mar. 19, 1936	
023	5:30 P.M. - Club Bagdad, Warwick Avenue, Warwick, looking northeast towards Pawtuxet River.	Mar. 19, 1936	
024	5:30 P.M. - Pawtuxet River at Warwick Avenue Bridge looking northwest showing water stage.	Mar. 19, 1936	
025	5:30 P.M. - Pawtuxet River Reservation, showing Department of Agriculture Buildings, Warwick Avenue, Cranston, R.I.	Mar. 19, 1936	
026	5:30 P.M. Pawtuxet River Reservation, State Nursery, East side of Warwick Avenue looking east.	Mar. 19, 1936	
027	8:00 A.M. - Regulation Reservoir showing submerged Regulation Dam.	Mar. 20, 1936	
028	8:15 A.M. - Braden Reservoir Dam.	Mar. 20, 1936	
029	8:30 A.M. - Scituate Reservoir Spillway. Two sets of flashboards in place, water at elevation 286.09 showing 601 M.G.D spillage.	Mar. 20, 1936	
030	8:35 A.M. - Scituate Reservoir Spillway Channel, showing 601 M.G.D. flow.	Mar. 20, 1936	
031	8:35 A.M. - Scituate Reservoir Spillway Channel, showing 601 M.G.D. flow.	Mar. 20, 1936	
032	Two-year old White Spruce transplants (125,000).	Apr. 9, 1936	
033	Two-year old White Spruce transplants (32,000).	Apr. 9, 1936	
034	Two-year old White Spruce transplants (25,000).	Apr. 9, 1936	

Photo #	Photo Description	Date	Notes
035	Four-year old Austrian Pine transplants; heeled in 12,000.	Apr. 9, 1936	
036		Apr. 13, 1936	
037		Apr. 13, 1936	
038		Apr. 13, 1936	
039		Apr. 13, 1936	
040		Apr. 13, 1936	
041			Missing
042		Apr. 13, 1936	
043		Apr. 13, 1936	
044		Apr. 13, 1936	
045	Scituate Reservoir Nursery seed beds (looking easterly).	Apr. 14, 1936	
046	Scituate Reservoir Nursery seed beds (looking southerly). Additional area being developed in background.	Apr. 14, 1936	
047	Scituate Reservoir Nursery, seed beds (northerly end) looking easterly.	Apr. 14, 1936	
048	Scituate Reservoir Nursery, general view of seed beds, looking southerly.	Apr. 14, 1936	
049	Scituate Reservoir Nursery, view of pond, looking easterly.	Apr. 14, 1936	
050	Scituate Reservoir Nursery, two-year old Red Pine seedlings (100,000) being transplanted from seed beds, looking westerly.	Apr. 14, 1936	
051	Scituate Reservoir Nursery, new area being developed for transplant beds under W.P.A., looking westerly.	Apr. 14, 1936	
052	Scituate Reservoir Nursery, five-year old White Cedar transplants (25,000).	Apr. 14, 1936	
053	Scituate Reservoir Nursery, two-year old White Spruce transplants (125,000).	Apr. 14, 1936	
054	Scituate Reservoir Nursery, two-year old Red Pine transplants (32,000).	Apr. 14, 1936	
055	Scituate Reservoir Nursery, two-year old Memlock transplants (25,000).	Apr. 14, 1936	
056	Four-year old Austrian Pine transplants, heeled in and ready to be planted in various locations around Scituate Reservoir (12,000).	Apr. 14, 1936	
057	Reforestation Nursery, pond.	Jun. 18, 1936	
058	Reforestation Nursery #2 - preparing transplant beds.	Jun. 18, 1936	

Photo #	Photo Description	Date	Notes
059	Reforestation Nursery #2 - transplant beds.	Jun. 18, 1936	
060	Reforestation Nursery #1 - seed beds.	Jun. 18, 1936	
061	Reforestation Nursery #1 - crassed enbankments.	Jun. 18, 1936	
062	Reforestation Nursery #1 - seed beds.	Jun. 18, 1936	
063	City Council Inspection Group.	Jun. 18, 1936	
064	Water Purification Works - Plumbing Equiment Testing Apparatus.	Jun. 26, 1936	
065	Water Purification Works - Plumbing Equiment Testing Apparatus.	Jun. 26, 1936	
066	Water Purification Works - Laboratory Office.	Jun. 26, 1936	
067	Water Purification Works - Laboratory.	Jun. 26, 1936	
068	Water Purification Works - Laboratory.	Jun. 26, 1936	
069	Water Purification Works - Laboratory.	Jun. 26, 1936	
070	Water Purification Works - Laboratory.	Jun. 26, 1936	
071	Water Purification Works - Laboratory.	Jun. 26, 1936	
072	Water Purification Works - General View.	Jun. 26, 1936	
073	Knight Brook Lane looking west showing section under construction.	Sept. 17, 1936	
074	Lower Fire Lane (South of Tower Lane) looking south at Culvert North of Knight Brook Lane.	Sept. 17, 1936	
075	Lower Fire Lane (North of Tower Lane) looking North from top of hill.	Sept. 17, 1936	
076	Lower Fire Lane (North of Tower Road) showing basic oil surface looking North.	Sept. 17, 1936	
077	Tower, Lane looking west showing road uner construction South of Tower.	Sept. 17, 1936	
078	Tower Road, between Fire Tower and lower Fire Lane, looking east.	Sept. 22, 1936	
079	Tower Road, between Fire Tower and lower Fire Lane, looking west.	Sept. 22, 1936	
080	Tower Road, East of Tower, showing road under construction looking east.	Sept. 22, 1936	
081	Knight Brook Lane looking southeast, showing pipe culvert and fill.	Sept. 22, 1936	
082	Knight Brook Lane looking southeast, showing Stone Culvert.	Sept. 22, 1936	
083	Tower Road, between Tower and lower Fire Lane, showing grading of trench for gutter.	Sept. 22, 1936	

Photo #	Photo Description	Date	Notes
084	Tower Road looking northwest, showing Knight Burial Plot after clearance.	Sept. 22, 1936	
085	Knight Brook Lane looking east, showing culvert approach first west of Lower Fire Lane South of Tower Road.	Sept. 22, 1936	
086	Knight Brook Lane looking west.	Sept. 22, 1936	
087	Knight Brook Lane looking east showing stone wall.	Sept. 22, 1936	
088	Knight Brook Lane looking west just north of gravel bank, showing wall and part of grassed slope.	Sept. 22, 1936	
089	Old Plainfield Pike near gate looking east.	Sept. 22, 1936	
090	Bathey Meeting House Lane showing view at gate at Saundersville Road before construction, looking north.	Sept. 24, 1936	
091	Bathey Meeting House Lane showing conditions before construction, looking north.	Sept. 24, 1936	
092	Bathey Meeting House Road showing conditions before construction, looking south.	Sept. 24, 1936	
093	Bathey Meeting House Lane at cove showing conditions before construction.	Sept. 24, 1936	
094	View of bank of disintergrated rock used for surfacing of lanes on Blackmar's Lane (upper bank).	Sept. 24, 1936	
095	View of lower bank of Blackmar's lane, showing disintergrated rock.	Sept. 24, 1936	
096	Junction of old Plainfield Pike lower Fire Lane looking southwest, showing walls.	Sept. 24, 1936	
097	Lower Fire Lan at first pipe culvert, southeast of Old Plainfield Pike.	Sept. 24, 1936	
098	Lower Fire Lane at Old Pond showing approaches to culvert.	Sept. 24, 1936	
099	Lower Fire Lane, south of Old Pond, showing wall and culvert.	Sept. 24, 1936	
100	Lower Fire Lane right angle corner at corner of private land, looking southeast, after putting down extra fill.	Sept. 24, 1936	
101	Tower Lan looking East at water's edge before construction.	Sept. 24, 1936	
102	Knight Brook Lane at Old Tunk Hill Road looking Southeast.	Sept. 29, 1936	

Photo #	Photo Description	Date	Notes
103	Lower Fire Lane (South of Tower Road) near Knight Brook Lane showing fill in detail.	Sept. 29, 1936	
104	Lower Fire Lane (South of Tower Road) near Knight Brook Lane looking West, showing general view of fill.	Sept. 29, 1936	
105	Tower Road, east of Old Tunk Hill Road, looking West, showing fill.	Sept. 29, 1936	
106	Tower Road, East of Col. Knight Cemetery, looking West, showing grassed slopes.	Sept. 29, 1936	
107	Lower Fire Lane, looking Northeast, showing Culvert.	Sept. 29, 1936	
108	Lower Fire Lane showing basic Oil surfacing.	Sept. 29, 1936	
109	Tower Road, East of Lower Fire Lane, looking East, showing removal and drilling of rock.	Sept. 29, 1936	
110	Tower Road opposite Fire Tower, looking East, showing section of road under construction.	Sept. 29, 1936	
111	Old Tunk Hill Road looking South, showing road before construction.	Sept. 29, 1936	
112	Old Tunk Hill Road looking North, showing road before construction.	Sept. 29, 1936	
113	Old Plainfield Pike looking West to West Road, showing spreading of finely screened disintergrated rock after seal coating.	Sept. 29, 1936	
114	Bathey Meeting House Fire Lane looking South to Plainfield Pike showing road before construction.	Sept. 30, 1936	
115	Bathey Meeting House Fire Lane looking North, showing road before construction, North of picture #114.	Sept. 30, 1936	
116	Bathey Meeting House looking South, showing section of road before construction, North of picture #115.	Sept. 30, 1936	
117	Bathey Meeting House Fire Lane looking North, showing road before construction, North of picture #116.	Sept. 30, 1936	
118	Bathey Meeting House Fire Lane looking South, showing section of road before construction, North of picture #117.	Sept. 30, 1936	

Photo #	Photo Description	Date	Notes
119	Bathey Meeting House Fire Lane looking North, showing section of road before construction, North of picture #118.	Sept. 30, 1936	
120	Bathey Meeting House Fire Lane looking South, showing section of road before construction, North of picture #119.	Sept. 30, 1936	
121	Bathey Meeting House Fire Lane looking North, showing section of road before construction, North of picture #120.	Sept. 30, 1936	
122	Bathey Meeting House Fire Lane looking North, showing section of road before construction, North of picture #121.	Sept. 30, 1936	
123	Bathey Meeting House Fire Lane looking South, showing section of road before construction, North of picture #122.	Sept. 30, 1936	
124	Bathey Meeting House Fire Lane looking North, showing section of road before construction, North of picture #123.	Sept. 30, 1936	
125	Bathey Meeting House Fire Lane looking Northwest, before construction, showing section at Valley where fill will be needed.	Sept. 30, 1936	
126	Old Tunk Hill Road looking Southeast to West Road, showing excavation of gutter.	Oct. 2, 1936	
127	Old Tunk Hill Road looking East, showing road under construction.	Oct. 2, 1936	
128	Lower Fire Lane looking South to Tower Road, showing seal coating.	Oct. 2, 1936	
129	Old Tunk Hill Road looking Southwest, showing sodding of bank.	Oct. 2, 1936	
130	Tower Road looking East, showing road under construction.	Oct. 2, 1936	
131	Tower Road, East of lower Fire Lane looking East, showing removal of stone with tractor.	Oct. 2, 1936	
132	Tower Road, East of lower Fire Lane looking East, showing excavated rock.	Oct. 2, 1936	
133	Tower Road, West of lower Fire Lane looking East, showing section of lane after removal of stone.	Oct. 2, 1936	
134	Knight Brook Lane, South of West Road, showing cemented gutter and culvert.	Oct. 2, 1936	

Photo #	Photo Description	Date	Notes
135	Old Tunk Hill Road looking West to West Road, showing section of road over new location.	Oct. 2, 1936	
136	Tower Road, looking Northeast, showing construction of gutter.	Oct. 2, 1936	
137	Knight Brook Lane looking Southeast, showing section of fill.	Oct. 2, 1936	
138	Knight Brook Lane looking West, showing grading of lane.	Oct. 5, 1936	
139	Knight Brook Lane looking East, showing unloading of gravel for fill.	Oct. 5, 1936	
140	Knight Brook Lane looking West, shwoing section of grading.	Oct. 5, 1936	
141	Knight Brook Lane looking Northwest, showing grading of bank.	Oct. 5, 1936	
142	Old Plainfield Pike lookin West to West Road, showing road all finished.	Oct. 5, 1936	
143	Lower Fire Lane looking South, South of picture #150 taken October 7.	Oct. 5, 1936	
144	Lower Fire Lane looking South, South of picture #143.	Oct. 5, 1936	
145	Lower Fire Lane, Southeast of picture #146, looking North at intersection of Old Plainfield Pike showing finished road.	Oct. 5, 1936	
146	Old Plainfield Pike, East of picture #142, looking East, showing road as finished.	Oct. 5, 1936	
147	Lower Fire Lane, South of picture #145, looking North, showing road as finished.	Oct. 5, 1936	
148	Lower Fire Lane, South of picture #147, looking South, showing finished road.	Oct. 5, 1936	
149	Lower Fire lane, South of picture #148, looking North, showing finished road.	Oct. 5, 1936	
150	Lower Fire Lane North of Picture #145 taken October 5 and South of picture #143 taken October 5, looking North of Old Planfield Pike showing finished road.	Oct. 7, 1936	
151	Lower Fire Lane looking south, south of picture #152, showing finished road.	Oct. 7, 1936	
152	Lower Fire Lane looking north, south of picture #149 taken October 5, showing finished road.	Oct. 7, 1936	
153	Lower Fire Lane looking south, south of picture #154, showing finished road.	Oct. 7, 1936	

Photo #	Photo Description	Date	Notes
154	Lower Fire Lane looking north, south of picture #151, showing finished road.	Oct. 7, 1936	
155	Lower Fire Lane looking south, south of picture #153, showing finished road.	Oct. 7, 1936	
156	Lower Fire Lane looking west, showing culvert approach.	Oct. 7, 1936	
157	Lower Fire Lane looking south, south of picture #158, showing finished road.	Oct. 7, 1936	
158	Lower Fire Lane looking North, north of picture #155, showing finished road.	Oct. 7, 1936	
159	Lower Fire Lane looking south, south of picture #160, showing finished road.	Oct. 7, 1936	
160	Lower Fire Lane looking north, south of picture #157, showing finished road.	Oct. 7, 1936	
161	Lower Fire Lane looking south to Tower Road, south of picture #159, showing finished road.		
162	Knight Brook Lane looking east, showing fill at curve.	Oct. 9, 1936	
163	Knight Brook Lane looking east, showing section of fill.	Oct. 9, 1936	
164	Knight Brook Lane looking southwest, showing road under construction.	Oct. 9, 1936	
165	Knight Brook Lane looking west, showing gutter and sodded bank.	Oct. 9, 1936	
166	Knight Brook Lane looking east, showing section of fill.	Oct. 9, 1936	
167	Old Tunk Hill Road looking west, showing section of road at curve under construction.	Oct. 9, 1936	
168	Old Tunk Hill Road looking east, showing road under construction.	Oct. 9, 1936	
169	Knight Brook Lane looking east, showing unloading and spreading of gravel.	Oct. 9, 1936	
170	Knight Brook Lane looking west, showing section of grading.	Oct. 9, 1936	
171	Knight Brook Lane looking north, showing culvert.	Oct. 9, 1936	
172	Knight Brook Lane looking northwest, showing section of grading.	Oct. 9, 1936	
173	Knight Brook Lane looking west, showing section of fill.	Oct. 9, 1936	
174	Knight Brook Lane looking west, showing section of gravel fill.	Oct. 14, 1936	

Photo #	Photo Description	Date	Notes
175	Tower Road looking northwest to water, showing road before construction.	Oct. 14, 1936	
176	Tower Road looking east, showing road under construction.	Oct. 14, 1936	
177	Old Tunk Hill Road looking southeast, showing culvert under construction on new location of road.	Oct. 14, 1936	
178	Gravel Bank showing loading of gravel with shovel (Kent-Coventry).	Oct. 14, 1936	
179	Knight Brook Lane looking east, showing grade.	Oct. 14, 1936	
180	Knight Brook Lane looking west, showing fill.	Oct. 14, 1936	
181	Tower Road looking southeast, showing culvert under construction.	Oct. 14, 1936	
182	Lower Fire Lane, south of Tower Road, looking south at Knight Brook Lane showing section of road.	Oct. 14, 1936	
183	Lower Fire Lane, south of Tower Road, looking north showing fill north of picture #182.	Oct. 14, 1936	
184	Knight Brook Lane looking west, showing section of fill.	Oct. 14, 1936	
185	Knight Brook Lane looking west, showing section of gravel fill.	Oct. 14, 1936	
186	Field south of Old Tunk Hill Road, showing cutting of sod.	Oct. 21, 1936	
187	Knight Brook Lane looking east, showing grade; "Charron's Sec."	Oct. 21, 1936	
188	Knight Brook Lane looking west showing sodding "Farrell's Sec."	Oct. 21, 1936	
189	Lower fire land, south of Tower Road, looking north to Tower Road, showing grade "Smith's Sec."	Oct. 21, 1936	
190	Lower fire land, south of Tower Road, looking south to Tower Road, showing grade "Smith's Sec."	Oct. 21, 1936	
191	Knight Brook Lane looking west, showing application of oil to gutters.	Oct. 21, 1936	
192	Knight Brook lane looking east, showing section of oiled gutters.	Oct. 21, 1936	
193	Old Tunk Hill Road looking west to gate, showing section of fill on new location of road. "Lyon's Sec." south of Tower Road.	Oct. 21, 1936	

Photo #	Photo Description	Date	Notes
194	Lower fire lane looking south, showing grade. "Smith's Sec."	Oct. 21, 1936	
195	Old Tunk Hill Road looking east, showing road under construction, "Lyon's Sec."	Oct. 21, 1936	
196	Tower Road looking north, showing culvert under construction and road to Tower.	Oct. 21, 1936	
197	Knight Brook Lane looking west to West Road, showing spreading of disintergrated rock on road.	Oct. 21, 1936	
198	Knight Brook Lane looking from stone wall to West Road, showing oiled section of road.	Oct. 28, 1936	
199	Knight Brook Lane looking west to West Road, showing oil application.	Oct. 28, 1936	
200	Old Tunk Hill Road looking south showing culvert and sodded bank.	Oct. 28, 1936	
201	Knight Brook Lane looking southwest showing spreading of disintergrated rock on road.	Oct. 28, 1936	
202	Knight Brook Lane looking east showing screening.	Oct. 28, 1936	
203	Tower Road looking northwest from curve shwoing culvert and gutter drain under construction.	Oct. 28, 1936	
204	Old Tunk Hill Road looking south showing section of road under construction.	Oct. 28, 1936	
205	Knight Brook Lane looking southwest showing section of graded road.	Oct. 28, 1936	
206	Old Tunk Hill Road looking southwest, showing unloading of gravel for fill.	Oct. 28, 1936	
207	Gravel Bank showing shovel in operation.	Oct. 28, 1936	
208	Old Tunk Hill Road looking west showing road on new location.	Oct. 28, 1936	
209	Blackmar's Bank, showiing loading of disintergrated rock.	Nov. 25, 1936	
210	Town Road looking east showing road under construction.	Nov. 25, 1936	
211	Town Road looking east, east of road to Fire Tower, showing road under construction.	Nov. 25, 1936	
212	Knight Brook Lane, looking west to West Road, showing road as finished.	Nov. 25, 1936	

Photo #	Photo Description	Date	Notes
213	Knight Brook Lane, looking east showing road as finished, "East of picture #212."	Nov. 25, 1936	
214	Knight Brook Lane looking west, "East of picture #213", showing road as finished.	Nov. 25, 1936	
215	Knight Brook Lane looking east "East of picture #214" showing road as finished.	Nov. 25, 1936	
216	Knight Brook Lane looking west "East of picture #215" showing road as finished.	Nov. 25, 1936	
217	Knight Brook Lane looking east "East of picture #216" showing road as finished.	Nov. 25, 1936	
218	Knight Brook Lane looking east, "East of picture #217" at intersection of lower Fire Lane, showing road as finished.	Nov. 25, 1936	
219	Lower Fire Lane, "Tower Road to Knight Brook" looking south, showing road as finished.	Nov. 25, 1936	
220	Lower Fire Lane, "Tower Road to Knight Brook" looking north, showing road as finished.	Nov. 25, 1936	
221	Nursery, showing straw covering of beds for the winter.	Dec. 29, 1936	
222	Nursery, showing a different section.	Dec. 29, 1936	
223	Bathey Meeting House Road section - 3910 feet north of Plainfield Pike, looking east, to Reservoir, showing section of property.	Dec. 29, 1936	
224	Bathey Meeting House Road section - 4110 feet north of Plainfield Pike, looking west, showing clearance.	Dec. 29, 1936	
225	Bathey Meeting House Road section - 4700 feet north of Plainfield Pike, looking northeast, showing cleared section.	Dec. 29, 1936	
226	Bathey Meeting House Road section - 3180 feet north of Plainfield Pike, looking south, showing view of cleared land.	Dec. 29, 1936	
227	Bathey Meeting House Road section - 3180 feet north of Plainfield Pike, looking west, to Reservoir, showing clearance.	Dec. 29, 1936	
228	Bathey Meeting House Road section - 5860 feet north of Plainfield Pike looking southeast to Reservoir, showing clearance.	Dec. 29, 1936	

Photo #	Photo Description	Date	Notes
229	Bathey Meeting House Road section - 6927 feet north of Plainfield Pike looking south, showing clearance.	Dec. 29, 1936	
230	Bathey Meeting House Road showing section of cleared property.	Dec. 29, 1936	
231	Bathey Meeting House Road, east showing section of cleared property.	Dec. 29, 1936	
232	Bathey Meeting House Road looking west, showing section of cleared property, Station 4903.	Dec. 29, 1936	
233	Scituate Dam looking northwest, showing section of wall broken.	Dec. 29, 1936	
234	Scituate Dam looking southeast, showing section of wall broken and cap stones.	Dec. 29, 1936	
235	Scituate Dam looking south, showing easterly section of wall broken.	Dec. 29, 1936	
236	Scituate Dam looking west from top of wall, showing cap stones and section of wall damaged.	Dec. 29, 1936	
237	Water Purification Works - North Coagulation Basin - showing section of basin cleaned.	Jan. 4, 1937	
238	Purification Works - North Coagulation Basin - showing section of basin before cleaning.	Jan. 4, 1937	
239	Water Purification Works - North Coagulation Basin, showing section of basin cleaned.	Jan. 4, 1937	
240	Water Purification Works - North Coagulation Basin - looking to mixer, showing section of basin cleaned.	Jan. 4, 1937	
241	Purification Works - North Coagulation Basin - showing section of basin during process of cleaning.	Jan. 4, 1937	
242	Water Purification Works - North Coagulation Basin - showing section of basin during process of cleaning.	Jan. 4, 1937	
243	Water Purification Works - North Coagulation Basin - showing section of uncleaned basin.	Jan. 4, 1937	
244	Water Purification Works - North Coagulation Basin - showing section of uncleaned basin.	Jan. 4, 1937	

Photo #	Photo Description	Date	Notes
245	Batthey Meeting House Road looking north, showing section of road after blasting.	Jan. 27, 1937	
246	Batthey Meeting House Road looking south, showing section of road after blasting.	Jan. 27, 1937	
247	Batthey Meeting House Road looking east, at Atwood's estate, showing causeway before construction.	Jan. 27, 1937	
248	Batthey Meeting House Road looking West, at Atwood's estate, showing causeway before construction.	Feb. 4, 1936	
249	Batthey Meeting House Road at causeway near Atwood estate, showing causeway before construction.	Feb. 4, 1936	
250	Batthey Meeting House Gravel Bank at Saundersville Pike, showing gasoline shovel loading gravel.	Feb. 4, 1936	
251	View of portion of ledge off Elmdale Road.	Feb. 17, 1937	
252	General view of ledge off Elmdale Road.	Feb. 17, 1937	
253	Batthey Meeting House Lane looking south, toward gate at Plainfield Pike.	Feb. 17, 1937	
254	Batthey Meeting House Lane looking north from picture #253, after gravel grading and surfacing by Highway Department.	Feb. 17, 1937	
255	Batthey Meeting House Lane looking south of picture #254, showing road being constructed by Highway Department.	Feb. 17, 1937	
256	Batthey Meeting House Lane, view of culvert at outlet, and at gate at Plainfield Pike.	Feb. 20, 1937	
257	Batthey Meeting House Lane, view showing grading of banks.	Feb. 20, 1937	
258	Batthey meeting House Lane, view showing excavating on banks and for culvert.	Feb. 20, 1937	
259	Batthey Meeting House Lane, view showing excavating for culvert.	Feb. 20, 1937	
260	Batthey Meeting House Lane, view showing grading and rolling of road.	Feb. 20, 1937	

Photo #	Photo Description	Date	Notes
261	Batthey Meeting House Lane, view shoiwng the laying of cobblestone in the gutters.	Feb. 20, 1937	
262	Batthey Meeting House Lane, view showing excavating for gutters.	Feb. 20, 1937	
263			
264	Batthey Meeting House Lane, view of section of road under construction.	Feb. 20, 1937	
265	Batthey meeting House Lane, view of Road Hog Grader in operation.	Feb. 20, 1937	
266	River view Fire Lane, view of lane before construction looking north to gate at Plainfield Pike.	Feb. 20, 1937	
267	River view Fire Lane, view of lane before construction looking south - south of picture #266.	Feb. 20, 1937	
268	Batthey Meeting House Fire Lane, looking west showing edge stone as laid.	Feb. 26, 1937	
269	Batthey Meeting House Fire Lane, looking north, showing edge stone as laid.	Feb. 26, 1937	
270	River view Fire Lane, looking southeast, showing road under construction through woods.	Feb. 26, 1937	
271	River view Fire Lane, looking north, showing section of edge stone as laid.	Feb. 26, 1937	
272	Blackmar's Fire Lane, looking north to gate at Plainfield Pike, showing lane before construction.	Feb. 26, 1937	
273	Blackmar's Fire Lane, looking south, showing lane before contruction (south of picture #272).	Feb. 26, 1937	
274	Blackmar's Fire Lane, looking north, showing lane before construction (south of picture #273 of February 26th series).	Mar. 2, 1937	
275	Blackmar's Fire Lane, looking south, showing lane before contruction (south of picture #274).	Mar. 2, 1937	
276	Blackmar's Fire Lane, looking north, showing lane before construction (south of picture #275).	Mar. 2, 1937	
277	Blackmar's Fire Lane, looking south, showing lane before construction (south of picture #276).	Mar. 2, 1937	

Photo #	Photo Description	Date	Notes
278	River View Fire Lane, looking west to intersection of Blackmar's Lane, showing lane before construction.	Mar. 2, 1937	
279	Batley Meeting House Fire Lane at a point 2400ft. North of Plainfield Pike, looking southeast, showing runoff after a rain through an old culvert to be rebuilt.	Mar. 2, 1937	
280	River View Fire Lane, looking east, showing lane before construction.	Mar. 2, 1937	
281	River View Fire Lane, looking, west, showing lane before construction (west of picture #280).	Mar. 2, 1937	
282	River View Fire Lane, looking west to bridge near Wilbur Hollow Rd., showing lane before construction (west of picture #281).	Mar. 2, 1937	
283	River View Fire Lane, looking east, showing lane before construction (west of picture #282).	Mar. 2, 1937	
284	River View Lane, looking west of Wilbur Hollow Rd., showing lane before construction (west of picture #283).	Mar. 2, 1937	
285	Wilbur Hollow Fire Lane at intersection of River View Fire Lane, looking south to River View Cross Rds., showing lane before construction (southwest of picture #284).	Mar. 2, 1937	
286	Elmdale section - showing crew planting trees.	Mar. 24, 1937	
287	Old Hartford Pike, showing view of grass fire that occurred at 4:45 A.M.	Apr. 2, 1937	
288	Old Hartford Pike, showing view of grass fire that occurred at 4:45 A.M. on March 30, 1937.	Apr. 2, 1937	
289	Rocky Hill Road (Elmdale Section) showing view of grass fire that occurred at 3:30 A.M. on March 27, 1937	Apr. 2, 1937	
290	Rocky Hill Road (Elmdale Section) showing starting point of grass fire that occurred at 3:30 A.M. on March 27, 1937	Apr. 2, 1937	
291	Elmdale section - showing crew planting trees.	Apr. 2, 1937	
292	Method of planting - Inserting setter in ground.	Apr. 2, 1937	

Photo #	Photo Description	Date	Notes
293	Method of planting - Loosening soil and selecting trees.	Apr. 2, 1937	
294	Method of planting - Inserting tree in hole.	Apr. 2, 1937	
295	Method of planting - Heeling ground around tree.	Apr. 2, 1937	
296	Wilbur Hollow Fire Lane - looking south to intersection of River View Cross Road (south of picture #285) before construction.	Apr. 7, 1937	
297	River View Cross Road - looking east to Wilbur Hollow Road (west of picture #296) before construction.	Apr. 7, 1937	
298	River View Cross Road - looking west (west of picture #297) before construction.	Apr. 7, 1937	
299	Water Purification Works, 48" Wash Water Pipe - refinishing interior with Bitumastic Enamel applied hot.	Mar. 1937	
300	Water Purification Works, 48" Wash Water Pipe - refinishing interior with Bitumastic Enamel applied hot.	Mar. 1937	
301	Scituate Aqueduct - 60" line Hydro Station to Junction Chamber - interior of pipe refinished with Bitumastic Enamel.	Mar. 1937	
302	Testing apparatus for testing Bitumastic Enamel Coating.	Mar. 1937	
303	Pipe Yard - Apparatus for spinning on Bitumastic Enamel Coating on interior of small pipe.	Mar. 1937	
304	Pipe Yard - Pouring hot Bitumastic Enamel in small pipe to be spun.	Mar. 1937	
305	Pipe Yard - spinning Bitumastic Enamel Coating in small pipe.	Mar. 1937	
306	(missing)		
307	Tower Road (Tunk Hill Section) looking north to water showing road under construction.	Apr. 15, 1937	
308	River View Lane showing Keystone #4 grader in operation.	Apr. 15, 1937	
309	Wilbur Hollow Road at intersection of River View showing Trac-Tractor in operation.	Apr. 15, 1937	

Photo #	Photo Description	Date	Notes
310	Wilbur Hollow Road at intersection of River View Lane showing road under construction.	Apr. 15, 1937	
311	Nursery #1, section C, showing planting of 1 year old seedling of red and white pine.	Apr. 15, 1937	
312	Nursery #1, section C, showing planting of 1 year old seedling of red and white pine.	Apr. 15, 1937	
313	Nursery #1, showing sections B and C of transplants.	Apr. 15, 1937	
314	Nursery #1, Section A - showing seed beds of Spring of 1937.	Apr. 15, 1937	
315	Nursery #2 - showing American Arbor Vitae transplants of Spring of 1937.	Apr. 15, 1937	
316	Nursery #2 - showing American Arbor Vitae transplants.	Apr. 15, 1937	
317	Nursery #2 - preparing soil for planting.	May 18 1937	
318	Blackmar's Lane looking south (south of picture #320) showing lane before construction.	May 18 1937	
319	Blackmar's Lane looking north - north of picture #318 and south of picture #276 of March 21, 1937 - showing lane before construction.	May 18 1937	
320	Blackmar's Lane looking south (south of picture #321) showing lane before construction.	May 18 1937	
321	Blackmar's Lane looking north (north of picture #320 and south of picture #318) showing lane before construction.	May 18 1937	
322	Blackmar's Lane looking south (south of picture #323) showing lane before construction.	May 18 1937	
323	Blackmar's Lane looking north (north of picture #322 and south of picture #320) showing lane before construction.	May 18 1937	
324	Blackmar's Lane looking South (south of picture #325) showing lane before construction.	May 18 1937	
325	Blackmar's Lane looking north (north of picture #324 and south of picture #322) showing lane before construction.	May 18 1937	

Photo #	Photo Description	Date	Notes
326	Blackmar's Lane looking south (south of picture #327) showing lane before construction.	May 18 1937	
327	Blackmar's Lane looking south to intersection of River View Crossroads (south of picture # 280 and north of picture #278 of March 21, 1937) showing lane before construction.	May 18 1937	
328	Batley Meeting House Road looking south to gate, showing top dressing before seal coating.	May 18 1937	
329	Batley Meeting House Road looking north (north of picture #328) showing top dressing before seal coating.	May 18 1937	
330	Batley Meeting House Road looking north showing top dressing of road.	May 17 1937	
331	Batley Meeting House Road looking south, showing road under construction.	May 17 1937	
332	Batley Meeting House Road looking south, showing section of edge stone as laid.	May 17 1937	
333	Tower Road (Tunk Hill Section) looking northeast - same section as picture #307 of April 15, 1937 - showing road before seal coating.	May 17 1937	
334	Tower Road (Tunk Hill section) looking northeast to water, showing road before seal coating.	May 17 1937	
335	Tower Road on west side (Tunk Hill section) looking south, showing trench for drainage of spring under road.	May 17 1937	
336	Batley Meeting House Road looking north, showing section of fill.	May 17 1937	
337	Batley Meeting House Road looking north, showing road under construction.	May 17 1937	
338	Batley Meeting House Road looking south, showing road under construction.	May 17 1937	
339	Batley Meeting House Road looking south to gate, showing seal coating.	May 17 1937	
340	Batley Meeting House Road looking north, showing seal coating.	May 17 1937	
341	Batley Meeting House Road looking north, showing seal coating.	May 17 1937	

Photo #	Photo Description	Date	Notes
342	Batthey Meeting House Road looking south showing application of seal coating.	Jul. 13, 1937	
343	Batthey Meeting house Road looking south, showing oiled and graveled sections of road.	Jul. 13, 1937	
344	Batthey Meeting House Road looking northeast showing section of edge stone.	Jul. 13, 1937	
345	Batthey Meeting House Road looking north showing side of road as graded.	Jul. 13, 1937	
346	Batthey Meeting House Road looking north, showing section of road before oil application.	Jul. 13, 1937	
347	Batthey Meeting House Road looking south, showing view of lane under construction. (section north of cemetery.)	Jul. 13, 1937	
348	Batthey Meeting House Road looking north, showing side of road as graded.	Jul. 13, 1937	
349	Batthey Meeting House Road looking south, showing view of lane as finished.	Jul. 13, 1937	
350	Batthey Meeting House Road looking north (north of picture #349) showing road as finished.	Jul. 13, 1937	
351	Batthey Meeting House Road looking south, (north of picture #350) showing road as finished.	Jul. 13, 1937	
352	Batthey Meeting House Road looking north, (north of picture #351) showing road as finished.	Jul. 13, 1937	
353	Batthey Meeting House Road looking south (north of picture #352) showing road as finished.	Jul. 13, 1937	
354	Batthey Meeting House Road looking north (north of picture #353) showing road as finished.	Jul. 15, 1937	
355	Batthey Meeting House Road looking south (north of picture #354) showing road as finished.	Jul. 15, 1937	
356	Tunk Hill section (east of Tower Road), showing drain as built, looking northeast.	Jul. 15, 1937	

Photo #	Photo Description	Date	Notes
357	Tunk Hill section (east of Tower Road), north of picture #356, looking south, showing drain as built.	Jul. 15, 1937	
358	Tunk Hill section east of Tower Road (north of picture #357) looking southwest showing drain as built.	Jul. 15, 1937	
359	Tower Road, north of fire tower, showing spreading of sand over seal coating.	Jul. 15, 1937	
360	River View Road at Page's place, showing culvert under construction.	Jul. 15, 1937	
361	River View Road between angle G and H showing culvert under construction.	Jul. 15, 1937	
362	Batley Meeting House Road at Atwood Causeway (looking north) showing grading and rolling.	Jul. 15, 1937	
363	Tower Road (Old Tunk Hill) looking northwest to gate at West Road, showing road as finished.	Jul. 15, 1937	
364	Tower Road (Old Tunk Hill Road) east of picture #363, looking east showing road as finished.	Jul. 15, 1937	
365	Tower Road (Old Tunk Hill Road) east of picture #364 looking west, showing road as finished.	Jul. 15, 1937	
366	Tower Road (Old Tunk Hill Road) east of picture #365, looking east, showing road as finished.	no date	
367	Tower Road (Old Tunk Hill Road) east of picture #366 looking east to intersection of Old Trunk Hill and Tower Road, showing road as finished.	no date	
368	Tower Road (north east of picture #367 looking south to intersection of Old Tunk Hill, showing road as finished.	no date	
369	Tower Road (north of picture #368) looking north, showing road as finished.	no date	
370	Tower Road (north of picture #369) looking south, showing road as finished.	no date	
371	Tower Road (north of picture #370) looking north, showing road as finished.	no date	
372	Tower Road (north of picture #371) looking south showing road as finished.	no date	

Photo #	Photo Description	Date	Notes
373	Tower Road (north of picture #372) looking north to road of Fire Tower, showing road as finished.	no date	
374	Tower Road (north of picture #373) looking south, showing road as finished.	no date	
375	Tower Road (north of picture #374) looking north, showing road as finished.	no date	
376	Tower Road (north of picture #375) looking north, showing road as finished.	no date	
377	Tower Road (north of picture #376) looking south, showing road as finished.	no date	
378	Tower Road (north of picture #377 of series of July 22, 1937) looking north, showing finished road.	Jul. 23, 1937	
379	Tower Road (north of picture #378) looking south, showing road as finished.	Jul. 23, 1937	
380	Tower Road (north of picture #379) looking north to north of lower Fire Lane showing road as finished.	Jul. 23, 1937	
381	Tower Road (north of picture #380) looking south, showing finished road.	Jul. 23, 1937	
382	Tower Road (north of picture #381) looking south, showing road as finished.	Jul. 23, 1937	
383	Tower Road (north of picture #382) looking north to water, showing road as finished.	Jul. 23, 1937	
384	Nursery Road looking east, showing bridge over waste water brook.	Jul. 23, 1937	
385	Nursery Road looking north, showing outlet of bridge.	Jul. 23, 1937	
386	Nursery Road looking south showing inlet of bridge.	Jul. 23, 1937	
387	Waste water brook looking south from end of culvert from plant.	Jul. 23, 1937	
388	Nursery Road looking north intersection of Access Road showing road before repairing.	Aug. 3, 1937	
389	Nursery Road looking south (south of picture #388) showing road before repairing.	Aug. 3, 1937	
390	Nursery Road looking north (south of picture #389) showing road before repairing.	Aug. 3, 1937	

Photo #	Photo Description	Date	Notes
391	Nursery Road looking southeast (south of picture #390) showing road before repairing.	Aug. 3, 1937	
392	Nursery Road looking northwest (south of picture #391) showing road before repairing.	Aug. 3, 1937	
393	Nursery Road looking southeast (east of picture #392) showing road before repairing.	Aug. 3, 1937	
394	Nursery Road looking northwest (east of picture #393) showing road before repairing.	Aug. 3, 1937	
395	Nursery Road looking southeast (east of picture #394) showing road before repairing.	Aug. 3, 1937	
396	Nursery Road looking northwest (east of phot #395) showing road before repairing.	Aug. 3, 1937	
397	Nurseru Road looking southeast to intersection of East Road (east of picture #396) showing road before repairing.	Aug. 3, 1937	
398	(missing)		
399	Gravel bank on west side of River View Road (north of Wilbur Hollow Road) looking west, showing general view of loading.	Aug. 3, 1937	
400	River View Road looking south showing culvert as completed.	Aug. 5, 1937	
401	Dump truck #30 looking up at bottom from right hand side of truck shwoing bent chassis.	Aug. 5, 1937	
402	Dump truck #30 showing broken body beam and bent chassis.	Aug. 5, 1937	
403	Dump truck #30 showing broken body beam and bent chassis.	Aug. 5, 1937	
404	(missing)		
405	(missing)		
406	Nursery Road looking northwest showing section of road as scarified.	Aug. 24, 1937	
407	(missing)		
408	Nursery Road at brook showing demolishing of bridge.	Aug. 24, 1937	
409	Nursery Road at brook showing demolishing of bridge.	Aug. 24, 1937	

Photo #	Photo Description	Date	Notes
410	Nursery Road looking west showing view of road under construction.	Aug. 24, 1937	
411	Nursery Road at brook showing setting of crete conduit.	Aug. 24, 1937	
412	Nursery Road looking south at inlet to brook, showing concrete conduits.	Oct. 1, 1937	
413	Nursery Road looking southwest, showing concrete conduits.	Oct. 1, 1937	
414	Nursery Road at inlet to brook looking south.	Oct. 1, 1937	
415	Nursery Road at brook showing wall under construction.	Oct. 1, 1937	
416	Nursery Road at brook, showing view of wall.	Oct. 1, 1937	
417	River View Lane looking west, showing Lorain Shovel cutting hill.	Oct. 1, 1937	
418	Nursery Road looking north to dam, showing seal coating.	Oct. 1, 1937	
419	Nurseru Road looking south (south of picture #418) showing seal coating.	Oct. 1, 1937	
420	Nursery Road looking north, (south of picture #419) showing seal coating.	Oct. 1, 1937	
421	Nursery Road looking south, (south of picture #420) showing seal coating.	Oct. 1, 1937	
422	Spruce Brook at River View Road looking south to road.	Oct. 1, 1937	
423	Nursery road looking north to intersection of access showing road as finished.	Nov. 3, 1937	
424	Nursery Road looking south (south of picture #423) showing road as finished.	Nov. 3, 1937	
425	Nursery Road looking north (south of picture #424) showing road as finished.	Nov. 3, 1937	
426	Nursery Road looking south (south of picture #425) showing road as finished.	Nov. 3, 1937	
427	Nursery Road looking west (east of picture #426) showing road as finished.	Nov. 3, 1937	
428	Nursery Road looking east (east of picture #427) showing road as finished.	Nov. 3, 1937	
429	Nursery Road looking west (east of picture #428) showing road as finished.	Nov. 3, 1937	
430	Nursery Road looking east to intersection of east road, showing road as finished.	Nov. 3, 1937	

Photo #	Photo Description	Date	Notes
431	River View Road looking east showing north end of Spruce Brook Culvert.	Nov. 3, 1937	
432	River View Road looking east showing south end of Spruce Brook Culvert.	Nov. 3, 1937	
433	Bridge over Spruce Brook at River View Road, looking north showing wall construction.	Nov. 3, 1937	
434	Bridge over Spruce Brook at River View Road, looking east, showing wall construction.	Nov. 3, 1937	
435	River View Road at Spruce Brook Culvert, looking west, showing view of road under construction.	Nov. 18, 1937	
436	Spruce Brook, looking northwest, showing section of bridge under construction.	Nov. 18, 1937	
437	River View Road at Spruce Brook, looking northwest, showing bridge under construction.	Nov. 18, 1937	
438	River View Road at Spruce Brook looking west.	Nov. 18, 1937	
439	River View Road looking north to gate at Plainfield Pike, showing road as finished.	Nov. 24, 1937	
440	River View Road looking south (south of picture #439) showing road as finished.	Nov. 24, 1937	
441	River View Road looking north, (south of picture #440) showing road as finished.	Nov. 24, 1937	
442	River View Road looking south, (south of picture #441) showing road as finished.	Nov. 24, 1937	
443	River View Road looking north, (south of picture #442) showing road as finished.	Nov. 24, 1937	
444	River View Road looking south, (south of picture #443) showing road as finished.	Nov. 24, 1937	
445	River View Road looking north, (south of picture #444) showing road as finished.	Nov. 24, 1937	
446	River View Road looking south (south of picture #445) showing road as finished.	Nov. 24, 1937	
447	East Road (south of Waterman's Corners) looking west, showing land after clearing.	Mar. 7, 1938	
448	East Road (south of Waterman's corners) looking east, showing land before thinning.	Mar. 7, 1938	

Photo #	Photo Description	Date	Notes
449	East Road (south of Waterman's Corners) looking west (west of East Road) showing process of thinnin gnad burning.	Mar. 7, 1938	
450	East Road (south of Waterman's corners) west of East Road looking, showing thinned area.	Mar. 7, 1938	