

THE CITY OF PROVIDENCE
STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

RESOLUTION OF THE CITY COUNCIL

No. 333

Approved July 17, 1989

RESOLVED, That the Director of Public Works is requested to cause the sidewalk along 16 St. James Street to be repaired, the same having been damaged by tree roots.


IN CITY COUNCIL

JUL 13 1989

READ AND PASSED


PRES.


CLERK



Councilwoman Young (By Request)



Carol Young

Department of Public Works

"Building Pride In Providence"

APPLICATION FOR SIDEWALK REPAIR

NO. _____

DATE 6-26-99

TO: Director of Public Works
700 Allens Avenue
Providence, RI 02905

The undersigned hereby requests the Director of Public Works to
repair a sidewalk damaged by TREEROOTS in front of the premises of:

16 St. James St.

Providence RI 02907

Telephone # 401-273-0223

CHECK ONE: Concrete (☒) Asphalt () Other ()

Signed Carol J. Harrell (Simmons)
Property Owner

Same as above
Address

Please be advised that the sidewalk in front of your premises has been
checked by an Inspector from this office. The results of this inspection
reveals that the sidewalk DOES/DOES NOT warrant repair by the City.

Inspected by: _____ Date _____

REMARKS: _____

THE CITY OF PROVIDENCE
STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

RESOLUTION OF THE CITY COUNCIL

No. 334

Approved July 17, 1989

RESOLVED, That the Director of Public Works
is requested to cause the installation of a Guard Rail
along 90 Whittier Avenue.

IN CITY COUNCIL

JUL 13 1989

READ AND PASSED

Nicholas W. Emdin
PRES.

Rose M. Mandonen
CLERK

APPROVED

JUL 17 1989

John J. White
MAYOR

Councilwoman DiRuzzo (By Request)

THE CITY OF PROVIDENCE
STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS



RESOLUTION OF THE CITY COUNCIL

No. 334

Approved July 17, 1989

RESOLVED, That the Director of Public Works
is requested to cause the installation of a Guard Rail
along 90 Whittier Avenue.

A true copy,
Attest:

Rose M. Mendonca,
City Clerk.

December 15, 1989

This location was inspected on Dec. 15th by our engineering section
and no reason was seen to install a guardrail at this location

B. James Súzman, Director