

THE CITY OF PROVIDENCE
STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

RESOLUTION OF THE CITY COUNCIL

No. 318

Approved April 26, 1975

RESOLVED, that the Traffic Engineer is requested to cause the replacement of Missing Stop Signs along Christopher Street, at its' intersection with Windmill Street.

IN CITY COUNCIL

APR 17 1975

READ AND PASSED

Ralph Lignol PRES.
Vincent Caspary CLERK

APPROVED

MAYOR

Vincent Caspary
APR 26 1975

Councilman Peterson
and Councilman Walker

1. The first of the two
2. The second of the two
3. The third of the two
4. The fourth of the two
5. The fifth of the two
6. The sixth of the two
7. The seventh of the two
8. The eighth of the two
9. The ninth of the two
10. The tenth of the two

11. The eleventh of the two
12. The twelfth of the two
13. The thirteenth of the two
14. The fourteenth of the two
15. The fifteenth of the two
16. The sixteenth of the two
17. The seventeenth of the two
18. The eighteenth of the two
19. The nineteenth of the two
20. The twentieth of the two

21. The twenty-first of the two
22. The twenty-second of the two
23. The twenty-third of the two
24. The twenty-fourth of the two
25. The twenty-fifth of the two
26. The twenty-sixth of the two
27. The twenty-seventh of the two
28. The twenty-eighth of the two
29. The twenty-ninth of the two
30. The thirtieth of the two

FRANK A. TIBALDI
TRAFFIC ENGINEER
JAMES J. D'AGOSTINO
ASSISTANT TRAFFIC ENGINEER



VINCENT A. CIANCI, JR.
MAYOR

TRAFFIC ENGINEERING DEPARTMENT

60 ERNEST ST.

PROVIDENCE, R. I. 02905

781 - 4044

May 28, 1975

The Honorable City Council
Committee on Public Works
City Hall
Providence, Rhode Island

RE: Resolution No. 318
Dated 4/26/75

Gentlemen:

The Traffic Engineering Department has received the following resolution from your Committee and has taken the subsequent action:

Request: That the Traffic Engineer is requested to cause the replacement of missing "STOP" signs along Christopher Street at its' intersection with Windmill Street.

Disposition: This department has conducted a traffic survey of this intersection. Our data indicates that only one vehicle crossed Windmill Street during a two hour period. In addition, an accident analysis showed that there were no reported accidents in the past four years. Based on this information I feel that a traffic control is not warranted at this time.

Very truly yours,

A handwritten signature in cursive script, reading "Frank A. Tibaldi".

Frank A. Tibaldi
Traffic Engineer

FAT/it