


# RESOLUTION OF THE CITY COUNCIL

No. 341

Approved June 8, 2000

RESOLVED, That the Director of Public Works is requested to  
bait the following streets located in the Fifth Ward.

Pleasant Valley Parkway  
Justice Street  
Fallon Avenue  
Canton Street  
Berlin Street  
Tiffany Street  
Rankin Avenue  
Grosvenor Street  
Jastram Street  
Sharon Street  
Portions of Nelson Street, Academy Avenue and Rosebank  
Street

CITY COUNCIL  
JUN 1 2000  
READ AND PASSED  
  
PRES.  
CLERK

APPROVED

JUN 8 2000  
  
MAYOR

B. + 003

*Butler*  
DIRECTOR OF PUBLIC WORKS

# RESOLUTION OF THE CITY COUNCIL


No. 341

Approved June 8, 2000

RESOLVED, That the Director of Public Works is requested to  
bait the following streets located in the Fifth Ward.


- Pleasant Valley Parkway
- Justice Street
- Fallon Avenue
- Canton Street
- Berlin Street
- Tiffany Street
- Rankin Avenue
- Grosvenor Street
- Jastram Street
- Sharon Street
- Portions of Nelson Street, Academy Avenue and Rosebank Street

A true copy,  
Attest:



Michael R. Clement  
City Clerk

Be advised that due to staffing limitations, this department was unable to respond to the baiting request immediately. The sewers on the above name streets were baited once on July 29, 2000, August 6, 2000 <sup>or</sup> and August 25, 2000.



- 8/28/2000

Ferdinand C. Ihenacho, P.E., PTOE

# RESOLUTION OF THE CITY COUNCIL

No. 342

*Approved* June 8, 2000

RESOLVED, That the Director of Public Works is requested to  
cause the installation of a guardrail at 627 Manton Avenue.

CITY COUNCIL  
JUN 1 2000  
READ AND PASSED

PRES.

APPROVED

JUN 8 2000

MAYOR

Councilman Richard (By Request)


# RESOLUTION OF THE CITY COUNCIL

No. 342

Approved June 8, 2000

RESOLVED, That the Director of Public Works is requested to  
cause the installation of a guardrail at 627 Manton Avenue.


A true copy,  
Attest:



Michael R. Clement  
City Clerk

August 29, 2000

An inspection shows that there is no evidence/record of accident occurrence and no  
structures to be protected by the installation of a guardrail.



- 8/31/2000

Ferdinand C. Ihenacho, P.E., Director