

	Photo #	Photo Description	Corresponding Photo(s)	Date	Notes
Contract #21	0001	West end of camp, bunk houses in foreground. Looking east from about Station 103 on the tunnel centerline.		Dec. 4, 1922	
	0002	Blacksmith and machine shop looking northeast.		Dec. 4, 1922	
	0003	View of camp looking west from shaft office building on right, Foremen's house behind office building Superintendent's house on left behind water tower. Central heating plan in left foreground.		Dec. 4, 1922	
	0004	Compressor house looking northeast. Central heating plan on left.		Dec. 4, 1922	
	0005	Shaft opening, derrick and dumping platform looking east from near compressor house.		Dec. 4, 1922	
	0006	Scituate Tunnel Water bearing seam in north wall of tunnel at Station 102+78. About five feet east of east contact of trap dike.		Jun. 19, 1923	
	0007	Scituate Tunnel Floor of shaft Station 108+44 looking west from east tunnel pump chamber in right background.		Jun. 19, 1923	
	0008	Scituate Tunnel looking east in west tunnel at about Station 107.		Jun. 19, 1923	
	0009	Scituate Tunnel west heading from shaft at about Station 96.		Jun. 19, 1923	"Enlarge to about 7 inches, Point out lettering in ???"
	0010	East portal cut looking northwest from Station 185. Open cut excavation at extreme easterly end of contract, shows approach cut from steam shovel in foreground.		Oct. 2, 1923	

	Photo #	Photo Description	Corresponding Photo(s)	Date	Notes
	0011	East portal cut looking east from Station 181. General view at east end of contract. Excavation is about 3 feet above final grade. Camera is about at location of eastportal of tunnel.		Oct. 2, 1923	
	0012	East heading of tunnel being driven from shaft looking east from Station 130. Mucking by hand in heading of tunnel. Loaded much cars in the foreground, muck pile and face of heading in background.		Oct. 2, 1923	
	0013	From east end of spoil bank at shaft looking southwest. Spoil bank in foreground. Head frame, crushing and screening plant in center, blacksmith shop at right, compressor house on left.		Oct. 2, 1923	
	0014	Circular section of tunnel looking east from Station 5 near west portal. Pipe on left wall is blower pipe.		Oct. 2, 1923	
	0015	West portal of tunnel looking east from Station 4 showing portal cut.		Oct. 2, 1923	
	0016	West portal of tunnel looking east into tunnel from Station 4 showing incline for much cars.		Oct. 2, 1923	
	0017	Concrete chute and cars of concrete train at feet of shaft. Taken from west of shaft looking east.		Aug. 6, 1925	
	0018	Footing forms on right and finished footings on left. Taken near Station 116, looking west.		Aug. 6, 1925	
	0019	Meeting of headings of West Portal tunnel and tunnel west of shaft. Looking east from about Station 41. (Heading met at Station 41+80 on Feb. 13)		Feb. 14, 1925	

	Photo #	Photo Description	Corresponding Photo(s)	Date	Notes
	0020	Scituate Tunnel. Looking west from about Station 110. Shows finished arch and sidewalls and rear end of steel forms. Invert not yet placed.		Feb. 17, 1925	
	0021	Scituate Tunnel. Looking east from about Station 110. Shows finished arch and sidewalls. Invert not yet placed.		Feb. 17, 1925	
	0022	Scituate Tunnel. Looking west from about Station 42, showing forms and lagging of arch across sand seam. The concrete sidewalls in front were cast some weeks previously. The 10"x10" post is the center supports one of the 10"x10" timber caps of the permanent timbering.		Mar. 19, 1925	
	0023	Scituate Tunnel. Looking west from about Station 45, showing concrete lining through sand seams. Water dripping in foreground shows small amount of leakage after grouting.		Apr. 8, 1925	