

THE CITY OF PROVIDENCE
STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

RESOLUTION OF THE CITY COUNCIL

No. 45

Approved February 14, 1974

RESOLVED, that the Director of Public Works is requested to cause sidewalks along both sides of Chapin Avenue be inspected and that a report of the condition of the same be made to the Committee on Public Works.

IN CITY COUNCIL
FEB 7 1974
READ AND PASSED

Ernest Vespi

CLERK

APPROVED

MAYOR

Joseph A. Keenly
FEB 14 1974

General Benedict Hutton,
Councilman Strong,
Councilman W. L. L. and
Councilman Payne

RECEIVED

RECEIVED

RECEIVED



CITY OF PROVIDENCE, RHODE ISLAND
MAYOR JOSEPH A. DOORLEY, JR.

DEPARTMENT OF PUBLIC WORKS . 700 ALLENS AVENUE . 02905

Lawrence P. McGarry, Director

Joseph J. Campo, Deputy Director

March 6, 1974

-

Chairman of the Public Works Committee
Providence City Council
City Hall - Prov., R.I. 02903

Dear Sir:

RE: Sidewalk Inspection on Chapin Ave. from Parade St. to Expressway as requested
by Resolution #45

Enclosed herewith find a list of sidewalks on Chapin Avenue, and the condition of each, as requested by the City Council.

Sincerely,

A handwritten signature in cursive script, appearing to read "Everett A. Travisono".

Everett A. Travisono
Acting Director of Public Works

EAT:jlrc
Encs.

SIDEWALK INSPECTION
ON CHAPIN AVENUE FROM PARADE STREET
TO EXPRESSWAY AS REQUESTED
BY RESOLUTION #45

Date: March 6, 1974

House Number	Type	Condition
3	Cement	Good Condition
5 & 7	Cement	Entire Walk Poor Condition
11 & 13	Cement	Rebuild 10 Slabs
15 & 17	Cement	Good Condition
23	Cement	Rebuild 4 Slabs @Tree Roots
31	Cement	Good Condition
35	Asphalt	Good Condition
41	Asphalt	Entire Walk Poor Condition @Tree Roots
43	Asphalt	Good Condition
51	Cement	Good Condition
61-63	Cement	Rebuild 4 Slabs @Tree Roots
67	Asphalt	Good Condition
71	Cement	Good Condition
73	Cement	Good Condition
79-81	Asphalt	Good Condition
89	Asphalt	Good Condition
93-95	Cement	Good Condition
97-99	Asphalt	Entire Walk Poor Condition
103	Asphalt	Good Condition
107	Asphalt	Good Condition
134-Messer	Asphalt	Entire Walk Poor Condition
133--"	Cement	Good Condition
127	Asphalt	Good Condition
129	Cement	Good Condition
133	Cement	Good Condition
139	Cement	Good Condition
143	Cement	Rebuild Entire Driveway
147	Asphalt	Good Condition
151	Asphalt	Good Condition
155	Cement	Rebuild Entire Driveway
159	Cement	Good Condition
165	Cement	Rebuild 5 Slabs
51-Elery	Asphalt	Good Condition
175	Asphalt	Good Condition
179	Cement	Good Condition
183	Asphalt	Entire Walk Poor Condition
187	Cement	Rebuild 8 Slabs
191	Cement	Rebuild 2 Slabs @Tree
193	Cement	Good Condition
199	Cement	Entire Walk Poor Condition
@Freeway	Asphalt	Entire Walk Poor Condition

SIDEWALK INSPECTION
ON CHAPIN AVENUE FROM PARADE STREET
TO EXPRESSWAY AS REQUESTED
BY RESOLUTION #45

Date: March 6, 1974

House Number	Type	Condition
Cr.	Asphalt	Good Condition
204	Asphalt	Good Condition
200	Cement	Good Condition
196	Cement	Good Condition
192	Asphalt	Good Condition
188	Asphalt	Good Condition
184	Asphalt & Cement	Rebuild Cement Portion
180	Asphalt & Cement	Entire Sidewalk Poor Condition
174	Asphalt	Good Condition
164	Asphalt	Notices Served
160	Cement	Good Condition
154	Cement	Good Condition
152	Cement	Rebuild 7 Slabs
148	Asphalt	Good Condition
142	Cement	Good Condition
138	Cement	Good Condition
134	Cement	Good Condition
130	Cement	Good Condition
126	Cement	Good Condition
124	Asphalt	Good Condition
139-Messer	Asphalt	Good Condition
106	Asphalt	Entire Walk Poor Condition
104	Asphalt	Good Condition
100	Asphalt	Good Condition
96	Cement	Good Condition
90	Cement	Good Condition
88	Cement	Good Condition
82	Cement	Good Condition
74	Cement	Good Condition
72	Asphalt	Good Condition
68	Cement	Rebuild 5 Slabs
64	Asphalt	Good Condition
58	Asphalt & Cement	Entire Sidewalk Poor Condition
52	Cement	Rebuild 7 Slabs
50	Cement	Good Condition
46	Asphalt	Good Condition
42	Cement	Good Condition
36	Asphalt	Good Condition
34	Asphalt & Cement	Rebuild Cement Portion
22	Asphalt & Cement	Rebuild 8 Slabs
12	Cement	Rebuild 15 Slabs
Cr. Cranston	Cement	Good Condition