

	Photo #	Photo Description	Corresponding Photo(s)	Date	Notes
Contract #23	0001	90' Cableway dragline excavator tower in course if erection looking east.		Aug. 2, 1923	
	0002	In foreground cableway over culvert site. In left background, cableway dragline excavator tower looking east.		Aug. 2, 1923	
	0003	Culvert excavation forms from invert of 35 feet, section of culvert shows excavation for cut off wall at south end looking north.		Aug. 2, 1923	
	0004	Cableway over culvert site showing protection for telephone wires. Looking south.		Aug. 2, 1923	
	0005	Moswansicut river culvert. Pouring most southerly 35' section of west wing wall to elvation 246.		Aug. 31, 1923	
	0006	Moswansicut river culvert. Looking northerly showing portion of east wall to elevation 246.		Aug. 31, 1923	
	0007	Moswansicut river culvert. Looking southerly 20' of invert remains to be poured. Walls at elevation 246.		Aug. 31, 1923	
	0008	Moswansicut river culvert. Looking northerly. Pouring most southerly 35' section of west wing wall to elevation 246.		Aug. 31, 1923	
	0009	Cableway dragline excavator in operation.		Sept. 5, 1923	
	0010	Looking southerly. Cable dragline in operation barrow area in foreground; fill in background.		Sept. 23, 1923	
	0011	Looking northerly. Ashland culvert. Pouring a 35' section of lower floor of culvert between elevation 246 and 253.5.		Sept. 12, 1923	
	0012	Looking northerly. Tower of dragline excavator in foreground; fill in background.		Sept. 23, 1923	